



## **Vermeer Corporation**

Environmental Pella, IA 50219 USA

FIELD CAMPAIGN KIT # IK003175 DATE: 7 July 2015

For Dealer Reference: Service Bulletin # SVC2015-127

## TLR30LD and TLR30HD Safety Chain Replacement Kit

| CAMPAIGN<br>TYPE: | <ul><li>✓ Mandatory - Product Safety</li><li>☐ Mandatory</li><li>☐ Recommended</li></ul> | ☐ Special Consideration (Fix-as-Fail) Special Consideration (Information Only) |
|-------------------|--|--|
|                   |  | ☐ Free Product Safety Mailing  |

| MACHINE /<br>ATTACHMENT | Serial Numbers |  |             |
|-------------------------|----------------|--|-------------|
| MODEL(S):               | Included       | Excluded   | Kit Version |
| TLR30HD                 | 2065-2080      | 2073, 2074, 2078, 2080                                 | IK01        |
| TLR30LD                 | 3210-3257      | 3180, 3192, 3193, 3195, 3196,<br>3221, 3230, 3240-3257 | IK01        |



### **PURPOSE:**


# IMPROPER SAFETY CHAIN INSTALLATION SEPARATION FROM TOW VEHICLE POSSIBLE

During manufacturing, the safety chains may not have been installed properly. Incorrect installation of the safety chains may allow the trailer to become unhitched from the tow vehicle. **Death or serious injury is possible** if the trailer separates from the tow vehicle while being towed on a public highway. Property or equipment damage is possible.

#### **SPECIAL TOOLS AND CONDITIONS:**


### None

Remove and discard current safety chain (Ref A, Figure A).
 Figure A




2. Install new safety chains as shown (Figure B).


Figure B



- 3. Install one safety chain assembly (163733572) (Ref 1, Figure 1) with one bolt (Ref. D, Figure C) (296300789) and one flange hex nut (Ref. E, Figure C) (296300899) on left side of tongue frame. Repeat on right side of tongue frame.
- 4. Insert chains through loop (Ref F, Figure C).

Figure C





**5.** Complete the work completion certificate **(Ref. G, Figure D)** (296287039) provided and return it to Product Safety for labor reimbursement.


Product Safety Dept. Vermeer Mfg. Co. P.O. Box 200 Pella, Iowa 50219

or fax to: 641-621-7739

Figure D



| 6. | Remove Figure 1 and provide to unit owner to place with existing Parts Manual by attaching page to the customer's copy of the invoice or placing the page in the unit's manual storage box. |
|----|---|
|    |   |
|    |   |
|    |   |
|    |   |





UNIT OWNER COPY: Insert in Parts Manual for future reference.

| FIGURE 1 Parts List |           |  |              |  |  |  |
|---------------------|-----------|--|--------------|--|--|--|
| REF.<br>NO.         | PART NO.  | DESCRIPTION  | IK01<br>QTY. |  |  |  |
| 1                   | 163733572 | SAFETY CHAIN ASSEMBLY (Part 2 is reference)            | 2            |  |  |  |
| 2                   | 260534001 | SAFETY CHAIN - 2600#                                   | 2            |  |  |  |
| 3                   | 296300789 | SCREW-HFS50-13X1.25-GR8-YZ                             | 2            |  |  |  |
| 4                   | 296300899 | NUT-HEX FLG50-13-GR8-YZ                                | 2            |  |  |  |
| 5                   | 296287039 | WORK COMPLETION CERTIFICATE - SAFETY KIT               | 1            |  |  |  |
|                     |           | Kit IK013175 includes all items in Figure 1 Parts List |              |  |  |  |